


INSPECTION INFORMATION

Name Of Site Being Inspected restaurant #521

Notes Regarding Site aging infrastructure, internal grill with hood and proper ventilation.

Site Location



Date Of Inspection 02/28/2011

Time Of Inspection 13:13

INSPECTION CHECK LIST

- Fuse Box
- Antenna
- Sprinklers
- Fire Alarms
- Exits
- Fire Escape
- Proper Exhaust Location

CONTACT SIGNATURE



My Company
123 Main St
My City, My State, 12345

Safety Inspection

Date: 02/28/2011

Contact Signature _____

Contact Name At Site _____ Jane Doe